




ISO CAMERA OECF TEST CHART 1000:1

TRANSPARENCY



Contrast ratio 1000 : 1

For measuring procedures see ISO 14524.

step	density (ISO)	density chart
1	3.10	
2	2.32	
3	1.84	
4	1.48	
5	1.21	
6	0.98	
7	0.79	
8	0.62	
9	0.47	
10	0.33	
11	0.21	
12	0.10	
13	1.11	

Densities based on light source = 0
 Measuring equipment : Techkon RT 120 Densitometer

Frechen:

